

## FITNESS CERTIFICATE FOR SCHOOL BUILDING

1. Name of the officer : SHIBU .K.A
2. Name of the institution : NALANDA PUBLIC SCHOOL
3. Location with name of institution : KUTHAPADI ,THAMMANAM ,ERNAKULAM  
District/Sub-District : Sub District, Thrippunithura
4. Classification of building as per specified  
In col.4 of the application for fitness certificate : Permanent RCC 3284.91 m2
5. Period for which the certificate issued : 2018- 2019
6. Nature of defect if any : No
7. a)Foundation and basement : Pile foundation,RCC  
b)super structure : RCC column and brick work  
c) door and windows : Cheru Teak  
d) wood work wrought and put up :  
e)roof : RCC  
F) Flooring : Cement plastered over concret bed
8. Any major defects modified which will  
render the building unsafe in any manner : No
9. Whether maintenance work have been  
Done properly : Yes
10. whether the structure is sound or not  
for conducting classes : Sound under normal condition

Certified that the institution was inspected by me on 6-12-19, and found to be fit to conduct classes for the period 2019-2020 (academic year) under normal condition

Place: vytila

Date: 6-12-19

  
**KAVITHA N.P.**  
PRINCIPAL

Nalanda Public School  
Thammanam, Kochi-682 032



  
**MANAGER**

Nalanda Public School  
Thammanam, Kochi-682 032

  
**SECRETARY**

Nalanda Public School  
Thammanam, Kochi-682 032

